

HIGH SPEED FERRY PROPELLER CAVITATION DAMAGE REPAIR

ID: 8145

Industry: Marine
Application: VPF-Valves, Pipes and Fittings
Substrate: Bronze
Products: * Belzona 1311 (Ceramic R-Metal) ,
* Belzona 9111 (Cleaner & Degreaser) ,

Customer Location: Tuzla, ISTANBUL, TURKEY
Application Date: April 2019

Problem

Cavitation damage on ferry propellers causing lower hydrodynamic efficiency and less propulsion capabilities.



Photograph Descriptions

- * Cavitation damage on the propeller. ,
- * After surface preparation. ,
- * Application Belzona 1311 (Ceramic R-Metal). ,
- * The surface faired after Belzona application. ,

Application Situation

Cavitation damage on both propellers of high speed ferry. The damage is more intense on the blade leading edges. The damaged propellers causing ferry two operate with some vibration and less hydrodynamic efficiency.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-01. Propeller surface blasted in blasting cabin. Surface was cleaned with Belzona 9111 (Cleaner & Degreaser) after blasting. Immediately following surface preparation Belzona 1311 (Ceramic R-Metal) is applied on the surface. After the product is cured, the surface was grinded and faired to achieve smooth surface.

Belzona Facts

Propeller replacement would be very costly too time consuming. Low cost and parmanent solution with Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve