

BUTTERFLY VALVE REFURBISHED WITH BELZONA

ID: 815

Industry: Water / Wastewater

Application: CEP-Centrifugal Pumps

Substrate: Cast Iron

Products: * Belzona® 1321 (Ceramic & S Metal) ,
* Belzona® 2221 (MP-Fluid Elastomer) ,

Customer Location: Water supply station, Egypt

Application Date: July 2006

Problem

Body badly corroded and holed in places. In addition rubber seal on valve disc completely deteriorated.



Photograph Descriptions

- * General view of the valve ,
- * The worn out rubber seal ,
- * Rubber seal was perfectly cast ,
- * Valve rebuilt and coated, application complete ,

Application Situation

Butterfly valve in water distribution system.

Application Method

Corrosion protection was made in accordance with Belzona Know-How System Leaflet VPF-2. The rubber seal was cast in accordance with Belzona Know-How System Leaflet CEP-9.

Belzona Facts

Belzona performed complete repair and protection to the valve body, disc and rubber seals.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve