

Belzona renovate a process tank


ID: 8169

Industry: *Food & Drink*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Steel*
Products: ** Belzona 5892 ,*

Customer Location: *France*
Application Date: *January 2020*

Problem

The internal lining of the tank was corroded due to the products being acidic when they are at high temperatures.



Photograph Descriptions

* 1 - Tank after grit blasting 2 - During application of Belzona 5892 3 - Tank after complete coating ,

Application Situation

Internal lining of a wheat starch milk tank in a factory

Application Method

Application was carried out in accordance with Belzona System Leaflet TCC-5. The tank was previously grit blasted to remove the rust before applying 2 coats of Belzona 5892. Small retouches were made before the coating system was post-cured with steam.

Belzona Facts

The replacement of the tank would have cost €1,000,000 whereas the Belzona repair was 10 times less (€100,000). The customer was quick to chose Belzona as the previous competitor coatings have failed.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve