

Belzona Repair Strainers

ID: 8180

Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Namibia*
Application Date: *14 October 2019*

Substrate: *Cast iron*
Products: ** Belzona 1111 (Super Metal) ,*
** Belzona 1321 (Ceramic S-metal) ,*
** Belzona 5811 (Immersion grade) ,*

Problem

Strainers badly eroded



Photograph Descriptions

- * 1. Strainer badly corroded ,
- * 2. Strainer Flange ,
- * 3. After grid blast ,
- * 4. Final product done with Belzona 1111 and Belzona 1321, with Belzona 5811 on the outside. ,

Application Situation

Fishing vessel strainers

Application Method

Application was carried out according to the system leaflet SOS-1 & SOS-2

Belzona Facts

These strainers are very badly damaged and is very costly to repair or manufacture new ones. The only economical way to repair

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

then is with Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

