

Belzona 5892 Protects Cement Plant Walls

ID: 8198

Industry: General Industry
Application: WPA-Wall Problem Areas
Substrate: Steel
Products: * Belzona 5892 ,

Customer Location: Poland
Application Date: 2019

Problem

The temperature in the furnace bag filters has caused corrosion of the bag filter walls.



Photograph Descriptions

- * Oven bag filter before protection ,
- * Grit blasting filter surface ,
- * First Layer of Belzona 5892 ,
- * Oven bag filter after 2nd Layer of Belzona 5892 ,

Application Situation

Damaged walls of the furnace bag filters on a Cement plant.

Application Method

Abrasive grit blasting, dust removal of wall surfaces and bag filter sieves. Then a Belzona 5892 two coat system was applied.

Belzona Facts

A cost effective solution for the customer using Belzona 5892 was a key driver however the back up service and support from the local distributor was key to the client making the decision to use Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Copyright © Belzona International Limited 2024