

# Belzona 4111 repairs a floor in a manufacturing facility.

ID: 8201

Industry:

Customer Location: Poland

Application:

Application Date: 2019

Substrate: Concrete

Products: \* Belzona 4111(Magma-Quartz) ,  
\* Belzona 4151(Magma-Quartz resin) ,

## Problem

*Carts in a manufacturing facility were damaging the floor due to the heavy traffic, weight of the carts, and the steel wheels.*



## Photograph Descriptions

\* 1: Ensure cavity's are clean and prepared. 2: Fill cracks and cavities with Belzona 4111 3: Belzona 4111 composite application in liquid form 4: Completed Application ,

## Application Situation

Floor damage due to heavy traffic in a manufacturing facility.

## Application Method

The surface was prepared by cutting out the floor cracks and vacuuming the surface. Belzona 4151 was used to impregnate the floor then Belzona 4111 was applied.

## Belzona Facts

Little down time was crucial for the client in this manufacturing facility, which is why they opted for Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve