

# Dairy Farm Wash Station Protected with Belzona 4181

ID: 8202

Industry: Food & Drink

Customer Location: Poland

Application: FPA-Floor Problem Areas

Application Date: 2019

Substrate: Concrete

Products: \* Belzona 4111 (Magma- Quartz) ,  
\* Belzona 4181 (AHR Magma Quartz) ,  
\* Belzona 4911 ,

## Problem

Unsealing of the joints in the dairy plant wash station causes floor destruction.



## Photograph Descriptions

- \* Damaged chemically resistant floors ,
- \* Belzona 4111 around the drain. ,
- \* Application of Belzona 4181 ,
- \* Complete Application ,

## Application Situation

The floor in a wash station of a dairy plant had a number of issues due to the unsealing of joints.

## Application Method

The Application was completed in accordance with Belzona System Leaflet FPA-01. Removal of damaged concrete and leveling the pump work area. Belzona 4111 applied around the damaged drain area. Belzona 4181 used to provide a chemically resistance to the floor area then post cured by heating the Belzona 4181 for 4 hours.

## Belzona Facts

Belzona have an excellent chemical resistant range suitable for application on concrete.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve