

Dairy Farm Wash Station Protected with Belzona 4181

ID: 8202

Industry: *Food & Drink*

Customer Location: *Poland*

Application: *FPA-Floor Problem Areas*

Application Date: *2019*

Substrate: *Concrete*

Products: ** Belzona 4111 (Magma- Quartz) ,
* Belzona 4181 (AHR Magma Quartz) ,
* Belzona 4911 ,*

Problem

Unsealing of the joints in the dairy plant wash station causes floor destruction.



Photograph Descriptions

- * Damaged chemically resistant floors ,
- * Belzona 4111 around the drain. ,
- * Application of Belzona 4181 ,
- * Complete Application ,

Application Situation

The floor in a wash station of a dairy plant had a number of issues due to the unsealing of joints.

Application Method

The Application was completed in accordance with Belzona System Leaflet FPA-01. Removal of damaged concrete and leveling the pump work area. Belzona 4111 applied around the damaged drain area. Belzona 4181 used to provide a chemical resistance to the floor area then post cured by heating the Belzona 4181 for 4 hours.

Belzona Facts

Belzona have an excellent chemical resistant range suitable for application on concrete.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

