

BELZONA SAFEGUARDS BOTTLING PLANT

ID: 830

Industry: *General Industry*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *ST 37 Steel*
Products: ** Belzona® 1111 (Super Metal) ,*
** Belzona® 1321 (Ceramic S-Metal) ,*

Customer Location: *Bottling Plant, Amman*
Application Date: *January 2007*

Problem

Extensive deep pittings and corrosion all over the large ring led to loss of pressure.



Photograph Descriptions

- * Damaged ring ,
- * Surface preparation ,
- * Filling, forming, and coating completed ,
- * Back in operation after two days ,

Application Situation

Bottling ring 2.7 meters diameter severely eroded and corroded.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets GSS-8, GSS-9 & ENC-2.

Belzona Facts

Belzona saved the customer money plus significantly reduced downtime. A new ring would have cost \$70,000 (£34,942) plus two weeks lost production of 13 million bottles.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve