

# Paving slab walkway repair with Belzona

ID: 8305

Industry: Buildings & Structures

Customer Location: Scotland

Application: FPA-Floor Problem Areas

Application Date: 2019 & 2020

Substrate: Stone Paving Slabs

Products: \* Belzona 4111 (Magma Quartz),

\* Belzona 4911 (TX Conditioner),

## Problem

Removing & replacing the paving slabs would have been a highly disruptive & costly undertaking. A durable & aesthetically pleasing repair solution was required that could be applied to the slabs whilst they remained in place.



## Photograph Descriptions

- \* Paving slabs original ,
- \* Wear & weathering of the existing slabs ,
- \* Belzona 4111 colour matched & applied ,

## Application Situation

Marshalls paving slabs had been installed on a domestic walkway as step treads. These slabs had started to deteriorate through wear, age & weathering. The slabs had lost their original colour & now had a dull appearance. The slabs were then replaced at the expense of the installer but after a further six years the replacements had also deteriorated. A permanent solution was required.

## Application Method

The Belzona 4111 Base was colour matched to the original Marshalls paving slabs using the Grey/Sandstone shades & cement pigments. Belzona 4911 TX Conditioner was applied to the areas followed by the mixed Belzona 4111 Magma Quartz.

## Belzona Facts

By using the Belzona solution there was no need for the removal of the existing paving slabs. These slabs could remain in place whilst being protected by a hard wearing & aesthetically pleasing material.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

