

Paving slab walkway repair with Belzona

ID: 8305

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Stone Paving Slabs

Products: * Belzona 4111 (Magma Quartz) ,
* Belzona 4911 (TX Conditioner) ,

Customer Location: Scotland

Application Date: 2019 & 2020

Problem

Removing & replacing the paving slabs would have been a highly disruptive & costly undertaking. A durable & aesthetically pleasing repair solution was required that could be applied to the slabs whilst they remained in place.



Photograph Descriptions

- * Paving slabs original ,
- * Wear & weathering of the existing slabs ,
- * Belzona 4111 colour matched & applied ,

Application Situation

Marshall's paving slabs had been installed on a domestic walkway as step treads. These slabs had started to deteriorate through wear, age & weathering. The slabs had lost their original colour & now had a dull appearance. The slabs were then replaced at the expense of the installer but after a further six years the replacements had also deteriorated. A permanent solution was required.

Application Method

The Belzona 4111 Base was colour matched to the original Marshall's paving slabs using the Grey/Sandstone shades & cement pigments. Belzona 4911 TX Conditioner was applied to the areas followed by the mixed Belzona 4111 Magma Quartz.

Belzona Facts

By using the Belzona solution there was no need for the removal of the existing paving slabs. These slabs could remain in place whilst being protected by a hard wearing & aesthetically pleasing material.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve