

# Pharmaceutical Company selects Belzona 4181


ID: 8319

Industry: Food & Drink  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Concrete  
Products: \* Belzona 4181 (AHR Magma-Quartz) ,

Customer Location: Finland  
Application Date: July, 2020

## Problem

The historic flooring had insufficient gradient for the chemicals to lead into the channels therefore the chemicals were pooling on the floor close to the channel, the old channels had weld seams which was causing leaks. This year the client needed to repair the drain-channels in the process basement and the distillery. There were two different problems. Problem One: The old factory (to be taken out of production in a couple of years), the flooring around the channel was deteriorated and uneven, and caused chemical waste to be lying still, without running down in the channel for transportation to the waste treatment process. Problem Two: The distillery area, waste channels needed a coating, due to weld seams that had cracking. The client requested the bottom of the whole channel to be coated, and also the sides.



## Photograph Descriptions

- \* Problem of chemical sitting on the floor area ,
- \* Application of Belzona 4181 complete ,
- \* Waste Chemical Channel deteriorated. ,
- \* Waste Channel Repaired with Belzona 4181 ,

## Application Situation

Post Production Chemicals should lead to the waste treatment process through channels under the process equipment. The chemicals involved are Organic and Inorganic Acids, Alcohols, Alkalis, Halocarbons etc. For example strong Sulphuric Acid, Acetic acid (even glacial), Formic acid, Lye and different Alkalis and ketones etc. (Ammonia, Calcium-, Potassium- and Sodium Hydroxide,

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

Methylene Chloride, Acetone, Toluene

## Application Method

Belzona 4181 was applied in accordance with Belzona System Leaflet TCC-10.

## Belzona Facts

The client wanted a long last lasting system to repair the area to ensure it would achieve a minimum of two years in service before closing down this production area.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

