

BELZONA REPAIR OF FLOATING HOSES

ID: 836

Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: Oil Refinery, Philippines
Application Date: March 2007

Substrate: Rubber
Products: * Belzona® 2111 (D&A Hi-Build Elastomer) ,
* Belzona® 2131 (D&A Fluid Elastomer) ,

Problem

Rubber covers and flotation/insulation on fuel hoses was damaged by ships propeller during fuel loading and unloading.



Photograph Descriptions

- * Typical damage ,
- * New insulation being bonded in with Belzona ,
- * Final outer cover build-up and coating ,
- * Completed repair ,

Application Situation

Fuel transport hoses offshore

Application Method

The repair was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

Belzona Facts

Belzona is the recommended repair option for such repairs. Replacement too expensive and delays unacceptable.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve