

# BELZONA REPAIR OF FLOATING HOSES

ID: 836

Industry: Oil & Gas  
Application: SOS-Ships and Offshore Structures

Customer Location: Oil Refinery, Philippines  
Application Date: March 2007

Substrate: Rubber  
Products: \* Belzona® 2111 (D&A Hi-Build Elastomer) ,  
\* Belzona® 2131 (D&A Fluid Elastomer) ,

## Problem

Rubber covers and flotation/insulation on fuel hoses was damaged by ships propeller during fuel loading and unloading.



## Photograph Descriptions

- \* Typical damage ,
- \* New insulation being bonded in with Belzona ,
- \* Final outer cover build-up and coating ,
- \* Completed repair ,

## Application Situation

Fuel transport hoses offshore

## Application Method

The repair was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

## Belzona Facts

Belzona is the recommended repair option for such repairs. Replacement too expensive and delays unacceptable.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve