

Welding seams protection

ID: 8360

Industry: *Chemical & Petrochemical*
 Application: *TCC-Tanks and Chemical Containment Areas*
 Substrate: *Carbon steel*
 Products: *Belzona 1341,*

Customer Location: *Petrochemical company, Slovakia*
 Application Date: *October 2021*

Problem

Corrosion on welds. A protective coating was the only option to prevent corrosion.




Corrosion on the welding seams



Welding seams was coated by Belzona 1341



Welding seams was coated by Belzona 1341



After 4 years no damage was appeared.

Application Situation

Tank for gasoline storing shows corrosion on the welding seams.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3

Belzona Facts

Customer needed quick and quality repair. All welding seams were coated by Belzona 1341. Coating was done in 2016. After 4 years no damage was appeared.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA[®]
 Repair • Protect • Improve