Belzona Flexible Membrane Seals Leaking Concrete Garage roof

ID: 8394

Industry: Buildings & Structures Customer Location: Malacky, Slovakia

Application: RPA-Roof Problem Areas Application Date: 2015

Substrate: Concrete

Products: * Belzona 3111 (Flexible Membrane),

Problem

Water, leaking through the concrete roof, was falling on the warehous goods and damaging it.









Photograph Descriptions

- * 1. Leaking concrete garage roof,
- * 2. Application of Belzona 3911 to concrete surfaces,
- * 3. Application of Belzona 3111,
- * 4. Ready to use,

Application Situation

Leaking concrete garage roof

Application Method

Application completed in accordance with a modified version of Belzona Know-How System Leaflet RPA-10

Belzona Facts

Sun and rain are able to destroy a lot of roof protection systems. Belzona 3111 system shows to be long lasting and perfect protected water proof system.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve