# Belzona Protects Operators in a Sugar Refinery using Belzona 5871

ID: 8408

Industry: Sugar Customer Location: L'Aube region of France

Application: VPF-Valves, Pipes and Fittings
Substrate: Stainless Steel - Grade 316
Products: \* Belzona 5871 Belzona 9111,

### Problem

Operator safety was a major concern for the asset owners, when their operators are having to manually operate the purge valves due to the pipework transporting steam at 90°C, therefore being a hazard and exposing the operators to potentials burn inccidents. The internal microcavities obtained by the system as it expands, creates a high performance thermal barrier, insulating the thermal process and/or preserving the safety of the operators. The new contact temperature after using Belzona 5871 was 47°C.







Application Date: September 2020

## **Photograph Descriptions**

\* 1) Belzona 5871 Final System Backside near Walkway 2) Belzona 5871 Final System Backside near Walkway (Close-Up) 3) Belzona 5871 Final System Purge Valve Access ,

## **Application Situation**

Stainless steel pipework transporting steam at 90°C, is handled manually by operators when purging the system.

## **Application Method**

The application was done in accordance with a modified version of Belzona's VPF System Leaflets. Belzona 5871 was manually applied using a brush no larger than 20mm wide, with the bristles cut down to 25mm. The product was applied to achieve a thickness of of 6mm.

#### **Belzona Facts**

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

zona's innovation, th	nere are no other simil	lar products on the	market making Belz	ona the best choice a	as a market leader.