Pharmaceutical Plant uses Belzona Safety Grip System

ID: 8418

Industry: Food & Drink Customer Location: Switzerland
Application: FPA-Floor Problem Areas Application Date: May 2020

Substrate: Concrete

Products: * Belzona 4111 (Magma Quartz),

* Belzona 5231 (SG Laminate), * Belzona 1821 (Fluid Metal),

* Belzona 9211 (Supergrip Aggregate),

* Belzona 5233,

Problem

The exterior flooring was an issue when the Pharmaceutical Plant forklift trucks were operating outside, causing the forklifts to slip when loading and un-loading.









Photograph Descriptions

- * Image 1: Application of Belzona 5231,
- * Image 2: Strips of Belzona 5231,
- * Image 3: Close up,
- * Image 4: Final Application Complete,

Application Situation

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



The client required a form of grip system for exterior use to stop any potential accidents or problems.

Application Method

Areas of concrete were repaired with Belzona 4111. The Belzona 5231 was the applied in accordance with System leaflet FPA-8 to the concrete and then the Belzona 1821 and Belzona 9211 grip system was used to create a safety grip system then overcoated with Belzona 5233 for increased UV Stability.

Belzona Facts

Belzona was used due to already been applied in other areas of the plant and knowing that Belzona performs very well they opted for Belzona on this particular health and safety issue.