

BELZONA REPAIRS TO ROOFTOP EXHAUST DUCTING

ID: 843

Industry: *General Industry*
Application: *VPF-Valves, Pipes and Fittings*
Substrate: *Galvanized metal*
Products: *Belzona® 2211 (MP Hi-Build Elastomer)*

Customer Location: *Pet food manufacturer, MO*
Application Date: *April 2007*

Problem

Joints were leaking allowing escape of unpleasant gases into the neighbourhood leading to many complaints.



Photograph Descriptions

* First duct joint , * Close up of first joint repair , * Second joint repair ,

Application Situation

Rooftop exhaust ductwork

Application Method

Application carried out using a modified Belzona System VPF-11a

Belzona Facts

Years of successful repairs, some of them very difficult, gave client the confidence to proceed with Belzona repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve