

Belzona furniture repair

ID: 8482

Industry: Buildings & Structures
Application: ENC-Engines and Casings
Substrate: Chipboard
Products: * Belzona 1212 ,

Customer Location: Slovakia
Application Date: 2019

Problem

The user needed to use this wardrobe immediately, without any dismantling, with repair for a long time.



Photograph Descriptions

- * 1. Ripped out door hinge ,
- * 2. Belzona 1212 application ,
- * 3. Installation in short time ,
- * 4. Ready to use ,

Application Situation

After long time using was the wardrobe door hinge ripped out

Application Method

Application was carried out using adapted Know-How System Leaflet ENC-2.

Belzona Facts

User knows Belzona products from industry using. He needed quick, good and long- standing repair. Belzona 1212 was his genuine solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve