

Belzona solution repairs Olympic Swimming Pool

ID: 8552

Industry:

Application: GSS-Gaskets, Seals and Shims

Substrate: Metal

Products: * Belzona 1111 (Super Metal) ,
* Belzona 9111 (Degreaser) ,
* Belzona 2911 (Elastomer QD Conditioner) ,
* Belzona 2211 (MP Hi-Build Elastomer) ,

Customer Location: Tunisia

Application Date: April 2007

Problem

Corrosion beneath gaskets caused a damage to sealing faces



Photograph Descriptions

- * 1 : Olympic Swimming Pool ,
- * 2 : Under water window severely damaged ,
- * 3 : Fixation ,
- * 4 : Camera under water ,

Application Situation

Leakage of the under water window used for cameras

Application Method

The application was carried out in accordance with Belzona Leaflets GSS-2. the area was prepared by rough grinding as well as the pre-formed seal, cleaned by Belzona 9111. Then the cold repair with Belzona 1111. Belzona conditioner 2911 was applied to both prepared surfaces. Application of Belzona 2211 and seal fixation.

Belzona Facts

Low cost, fast et durable repair (still in good condition)

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve