

Repair of drinking water tank with Belzona 5811DW2

ID: 8560

Industry: *Food & Drink*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Concrete*
Products: ** Belzona 5811DW2 ,
* Belzona 4111 ,
* Belzona 4911 ,*

Customer Location: *Poland*
Application Date: *July 2021*

Problem

The concrete walls of the water tank had corroded over time leading to deterioration of the substrate subsequently leading to a poorer quality water quality.



Photograph Descriptions

- * Image 1: Inside of the Water Tank ,
- * Image 2: Re-Build of the Concrete using Belzona 4111 ,
- * Image 3: Spraying Belzona 5811DW2 ,
- * Image 4: Completed Application ,

Application Situation

Renovation of a Water tank on site using a Belzona Drinking Water approved coating.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Application Method

The Belzona products were applied in accordance with the Belzona System Leaflet TCC_5.

Belzona Facts

Belzona 5811DW2 is a WRAS approved coating for Potable Water, spray applied allowing for a quick and easy return to service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

