

BELZONA RE-SURFACES WATER PARK FLOORS

ID: 858

Industry: General Industry

Customer Location: Water Park - Oklahoma

Application: FPA-Floor Problem Areas

Application Date: May 2007

Substrate: Concrete

Products: Belzona® 5111 (Ceramic Cladding)
 Belzona® 9221 (Surefoot Aggregate White)

Problem

Painted floors in bathrooms and outside surfaces were wearing out on a yearly basis and the city was looking for a long term solution.



Photograph Descriptions

* Bathroom floors before application. , * Bathroom floors after Belzona® 5111 was applied. , * Outside surfaces before application. , * Outside surfaces after Belzona® 5111 application. ,

Application Situation

Bathroom floors and outside surfaces in a water park.

Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-8.

Belzona Facts

Belzona product was found to provide a long term solution compared to original paint system which required annual replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

