

BELZONA RE-SURFACES WATER PARK FLOORS

ID: 858

| | | | |
|--------------|--|--------------------|-----------------------|
| Industry: | General Industry | Customer Location: | Water Park - Oklahoma |
| Application: | FPA-Floor Problem Areas | Application Date: | May 2007 |
| Substrate: | Concrete | | |
| Products: | Belzona® 5111 (Ceramic Cladding) Belzona® 9221 (Surefoot Aggregate White) | | |

Problem

Painted floors in bathrooms and outside surfaces were wearing out on a yearly basis and the city was looking for a long term solution.



Photograph Descriptions

- * Bathroom floors before application. ,
- * Bathroom floors after Belzona® 5111 was applied. ,
- * Outside surfaces before application. ,
- * Outside surfaces after Belzona® 5111 application. ,

Application Situation

Bathroom floors and outside surfaces in a water park.

Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-8.

Belzona Facts

Belzona product was found to provide a long term solution compared to original paint system which required annual replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

| | |
|----------------|---------------------------|
| ISO 9001:2015 | Belzona products are |
| FS 695214 | manufactured under an ISO |
| ISO 14001:2015 | 9000 Registered Quality |
| EMS 695213 | Management System. |

www.belzona.com

