

# BELZONA SEALS UNSANITARY LEAKING FLOOR DRAIN IN FOOD PLANT

ID: 860

Industry: *General Industry*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete*  
Products: *\* Belzona® 4111 (Magma Quartz) ,*

Customer Location: *Pet food manufacturer, O'Fallon, MO*  
Application Date: *June 2007*

## Problem

*Leak around drain allowed waste product into the sanitary production packaging floor below.*



## Photograph Descriptions

- \* Unsanitary, leaking drain ,
- \* Surface prepared ,
- \* Belzona® 4111 installed ,
- \* Drain cover installed ,

## Application Situation

Waste drain on 2nd floor above production packing area.

## Application Method

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1.

## Belzona Facts

Only a small amount of product used to solve a health hazard and to meet American Baking Association standard of cleanliness. This client has a long history of successful Belzona applications.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve