

BELZONA SEALS UNSANITARY LEAKING FLOOR DRAIN IN FOOD PLANT

ID: 860

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4111 (Magma Quartz) ,

Customer Location: Pet food manufacturer, O'Fallon, MO
Application Date: June 2007

Problem

Leak around drain allowed waste product into the sanitary production packaging floor below.



Photograph Descriptions

- * Unsanitary, leaking drain ,
- * Surface prepared ,
- * Belzona® 4111 installed ,
- * Drain cover installed ,

Application Situation

Waste drain on 2nd floor above production packing area.

Application Method

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1.

Belzona Facts

Only a small amount of product used to solve a health hazard and to meet American Baking Association standard of cleanliness. This client has a long history of successful Belzona applications.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024