

Belzona Overhauls a Pump in a Waste Incineration Plant

ID: 8620

Industry: Power
Application: CEP-Centrifugal Pumps
Substrate: Steel
Products: * Belzona 1111 (Super-Metal) ,
* Belzona 1381 ,
* Belzona 1813 ,

Customer Location: Poland
Application Date: October 2021

Problem

After a local inspection, a technology was developed to repair damaged pump components based on a coating system that increases erosive resistance for demanding pump operating conditions.



Photograph Descriptions

- * 1 - Damaged Pump ,
- * 2 - Cracked Casing to be repaired with Belzona 1111 ,
- * 3 - Internal Lining coated Belzona 1381 ,
- * 4 - Completed Application ,

Application Situation

Duchting Pumpen MC 300-500 after many years of operation was damaged by numerous body cracks and other damage.

Application Method

The scope of work carried out with Belzona materials included, among others:

- repair of pump body crack
- replenishment of cavities, protection of the rotor and body

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

- restoration of the nominal load-bearing parameters of the structure of the cracked pump body
- regeneration of the retaining ring
- regeneration of the inner ring in the pump body All inline with Belzona system leaflet CEP-5

Belzona Facts

☑ Cost and time savings – thanks to the regeneration and restoration of damaged components, it was possible to avoid expensive purchases and long waits for new parts. ☑ Belzona coating system increased erosive resistance and protected the pump for harsh environments. After 6 months from the start of the pump, the customer gave us another similar pump for repair and regeneration.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

