

Industrial Floor coated with Belzona

ID: 8621

Industry: Buildings & Structures

Customer Location: Poland

Application: FPA-Floor Problem Areas

Application Date: August 2021

Substrate: Concrete

Products: * Belzona 4111 (Magma-Quartz),
* Belzona 5231 (SG Laminate),

Problem

Degradation of the floor surface could lead to the occurrence of potentially dangerous events, i.e. overturning the trolley, tripping within the production hall.



Photograph Descriptions

- * Image 1 - Damaged floor to be repaired with Belzona 4111 ,
- * Image 2 - Vacuuming up any loose debris and dust. ,
- * Image 3 - Roller Brush Application of Belzona 5231 ,
- * Image 4 - Completed Application ,

Application Situation

Maintaining the required hygiene and cleanliness of the production hall. Unevenness of the floor surface and damage to the pedestals arose as a result of intensive vehicular traffic of internal transport.

Application Method

Replenishment of cavities, repair of the floor surface, making a new smooth washable surface. Low-cost technology compared to traditional methods, applied in-accordance with Belzona system leaflet FPA-3.

Belzona Facts

The client can be assured that when washing with chemicals they will not have to worry about the degradation of the coating or concrete.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

