

# Belzona protects clarifier track

ID: 8622

Industry: Water / Wastewater  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Concrete  
Products: \* Belzona 4911 ,  
\* Belzona 4111 (Magma-Quartz) ,

Customer Location: Italy  
Application Date: 2021

## Problem

The damage on the track on the clarifier needed to be rebuilt to a smooth surface in order to allow the operation of the 'crane' unit.



## Photograph Descriptions

- \* 1. Removal of spooled and damaged concrete ,
- \* 2. Removal of spooled and damaged concrete ,
- \* 3. Conditioning of the substrate ,
- \* 4. Completed application ,

## Application Situation

The track on an effluent clarifier had become damaged over time, so a solution was needed to rectify this.

## Application Method

Any loose material was removed and shuttering installed to the required height. The substrate was conditioned with Belzona 4911 and rebuilt with Belzona 4111.

## Belzona Facts

The works to repair the entirety of the 80m tank circumference were completed in just 5 days.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve