

# BELZONA RESEALS AROUND ROOFTOP A/C UNITS

ID: 863

Industry: Pulp & Paper  
Application: RPA-Roof Problem Areas  
Substrate: Tar, Aluminum paint and Belzona® 3111  
Products: Belzona® 3111 (Flexible Membrane)

Customer Location: Chic Lumber Co, OFallon, MO  
Application Date: July 2007

## Problem

Over zealous painter overcoated Belzona repair with an aluminum paint that caused the Membrane to crack leading to roof leaks



## Photograph Descriptions

\* Start of the application , \* Sheet being incorporated in Belzona® 3111 coating , \* Application continuing , \* All sides waterproofed ,

## Application Situation

This unit was successfully sealed with Belzona® 3111 over 10 years ago.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8

## Belzona Facts

Previous success of the Belzona® 3111 and reluctant admission of mistakenly applying aluminized paint over the Belzona® 3111 coating lead to re-installation of the Belzona. Reroofing was the alternative to repairing a small portion of the 25,000 sq ft roof.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024