

BELZONA RESEALS AROUND ROOFTOP A/C UNITS

ID: 863

Industry: *Pulp & Paper*
Application: *RPA-Roof Problem Areas*
Substrate: *Tar, Aluminum paint and Belzona® 3111*
Products: *Belzona® 3111 (Flexible Membrane)*

Customer Location: *Chic Lumber Co, OFallon, MO*
Application Date: *July 2007*

Problem

Over zealous painter overcoated Belzona repair with an aluminum paint that caused the Membrane to crack leading to roof leaks



Photograph Descriptions

* Start of the application , * Sheet being incorporated in Belzona® 3111 coating , * Application continuing , * All sides waterproofed ,

Application Situation

This unit was successfully sealed with Belzona® 3111 over 10 years ago.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8

Belzona Facts

Previous success of the Belzona® 3111 and reluctant admission of mistakenly applying aluminized paint over the Belzona® 3111 coating lead to re-installation of the Belzona. Reroofing was the alternative to repairing a small portion of the 25,000 sq ft roof.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve