

# BELZONA REPAIR TO POWER PLANT COAL BELT

ID: 874

Industry: Power

Application: SHM-Solids Handling Machinery

Customer Location: Power Station, Missouri

Application Date: 2007

Substrate: Rubber

Products: Belzona® 2111 (D&A Hi-Build Elastomer)

## Problem

Belt developed a large burn hole. This rendered the belt unusable until fixed.



## Photograph Descriptions

\* Hole in the belt being prepared , \* Preparation completed , \* Completed application , \* Completed application ,

## Application Situation

One of a series of large belts used to bring coal from the coal yard to the plant.

## Application Method

Belt was repaired according to Belzona System Laflet SHM-1

## Belzona Facts

The company that usually repairs their belts takes a long time to respond to service requests and are very expensive. They needed the repair completed quickly. The belt was repaired in a matter of hours and the plant now uses Belzona for all belt repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025