

BELZONA REPAIR TO POWER PLANT COAL BELT

ID: 874

Industry: Power

Customer Location: Power Station, Missouri

Application: SHM-Solids Handling Machinery


Application Date: 2007

Substrate: Rubber

Products: Belzona® 2111 (D&A Hi-Build Elastomer)

Problem

Belt developed a large burn hole. This rendered the belt unusable until fixed.



Photograph Descriptions

* Hole in the belt being prepared , * Preparation completed , * Completed application , * Completed application ,

Application Situation

One of a series of large belts used to bring coal from the coal yard to the plant.

Application Method

Belt was repaired according to Belzona System Laflet SHM-1

Belzona Facts

The company that usually repairs their belts takes a long time to respond to service requests and are very expensive. They needed the repair completed quickly. The belt was repaired in a matter of hours and the plant now uses Belzona for all belt repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve