

# Internal Joint Repair to Stainless Steel Pasteuriser at a Brewery

ID: 8753

Industry: Food & Drink  
Application: GSS-Gaskets, Seals and Shims  
Substrate: Stainless Steel  
Products: \* Belzona 1511 (Super HT-Metal) ,

Customer Location: Derbyshire, UK  
Application Date: March 2022

## Problem

A stainless steel pasteurising bottling line had a large leak from a joint. The pasteurizer could not be disassembled to replace the gasket and therefore the only option was to seal the joint in situ.



## Photograph Descriptions

\* 1. Leaking pasteuriser 2. Surface of the seam prepared prior to repair 3. Belzona 1511 used to bond plates in place 4. Completed repair ,

## Application Situation

The internal seal between two sections of the stainless steel pasteurising bottling line had developed a leak.

## Application Method

All of the exposed mastic material between the joint was removed. The repair area was then mechanically prepared using a hand-held industrial surface preparation tool. Belzona 1511 was then applied to both the joint and pre-formed plates using a stiff brush to eliminate air entrapment. The plates were then bonded onto the substrate.

## Belzona Facts

Taking the equipment offline would have resulted in a two-week outage for the brewery and replacement of the equipment was estimated at £30,000. The Belzona solution lent itself perfectly to this repair as it could be applied in-situ with no hot work. In addition, Belzona Applicators are trained to work in confined spaces allowing them to safely apply this repair at a fraction of the cost of alternatives.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve