

EXPANSION JOINT AT HOSPITAL SEALED WITH BELZONA

ID: 879

Industry: *Buildings & Structures*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: *Belzona® 4111 (Magma Quartz)*
 Belzona® 2221 (MP Fluid Elastomer)

Customer Location: *Hospital, Missouri*
Application Date: *2007*

Problem

Expansion joints in the hospital had become a tripping hazard



Photograph Descriptions

* View of joint with kick plate removed , * Application of Belzona® 4111 , * Application of Belzona® 2221 , * Completed application ,

Application Situation

Expansion joints in corridor in need of repair

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and -6.

Belzona Facts

The hospital needed a fast-curing and reliable method for repairing expansion joints that were creating trip hazards for patients.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025