

BELZONA REPAIRS SCHOOLS CHILLER

ID: 880

Industry: Buildings & Structures
Application: HEX-Heat Exchangers
Substrate: Carbon Steel
Products: * Belzona® 1311 (Ceramic R-Metal) ,
* Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Elementary School, St. Louis, Missouri
Application Date: 2007

Problem

Years of service had caused extensive corrosion on the chiller tube sheet face.



Photograph Descriptions

- * Corroded tube sheet face ,
- * Application in progress ,
- * Completed application ,
- * Completed application ,

Application Situation

Corroded chiller face

Application Method

Application was completed in accordance with Belzona System Leaflet HEX-1.

Belzona Facts

School officials were aware of Belzonas reputation for quality and reliability.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve