

Belzona Weatherproofs Instrumentation Control Roof

ID: 8875

Industry: Chemical & Petrochemical
Application: RPA-Roof Problem Areas
Substrate: Bituminous Roofing Felt
Products: * Belzona 3111 (Flexible Membrane) ,
* Belzona 3921 (GSC Surface Conditioner) ,
* Belzona 9311 (Reinforcement Sheet) ,

Customer Location: Caen, France
Application Date: September 2022

Problem

The roof covered in gravel had been leaking water into the building for years. This issue worsened after the installation of a new skylight over 12-months ago, causing serious damage to the buildings internal walls.



Photograph Descriptions

- * 1). Roof after the gravel was removed. ,
- * 2). Close-up of are where roofing felt had to be removed due to rot. ,
- * 3). Post-application of Belzona Stripe Coating on all edges and entry-points around the skylight. ,
- * 4). Finished application with 2x coats of Belzona 3111 and Reinforcement Sheet. ,

Application Situation

Building roof (240m²) of an Instrumentation & Control office within a Petrochemical Depot.

Application Method

The application was carried out in accordance with Belzona System Leaflet RPA-01 & RPA-02.

Belzona Facts

The client unfortunately had no alternative due to the building being in an ATEX rated zone, and no other company being able to

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

supply a cold-applied solution with such a quick turnaround due to the wet season looming in.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

