

# BELZONA REPAIRS NEW HEAVY EQUIPMENT TIRE

ID: 889

Industry: General Industry

Customer Location: Equipment Dealership, South Central Kansas

Application: SHM-Solids Handling Machinery

Application Date: June, 2007

Substrate: Rubber

Products: \* Belzona® 2311 (SR Elastomer) ,

## Problem

When the transport unloaded this brand new loader, the tire was damaged.



## Photograph Descriptions

- \* Damaged portion of the tire ,
- \* Roughened surface ,
- \* Surface conditioned ,
- \* Tire rebuilt with Belzona® 2311 ,

## Application Situation

New front end loader being delivered to the local dealership.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The surface was prepared with a roughing brush and conditioned with Belzona® 2911 (QD Conditioner). The gouges in the rubber tire cover were rebuilt with Belzona® 2311.

## Belzona Facts

The Belzona repair was completed quickly and its excellent adhesion and abrasion resistance will ensure it continues to perform in service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve