

# Belzona Superwrap 2 system repairs storage tank

ID: 8945

Industry: *Chemical & Petrochemical* Customer Location: *Scotland*  
Application: *TCC-Tanks and Chemical Containment Areas* Application Date: *January 2023*  
Substrate: *Carbon steel*  
Products: *Belzona 1111 (Super Metal), Belzona 1981 (SuperWrap II)*

## Problem

A leak had developed in a storage tank due to corrosion.



Leaking area



Belzona 1111 & Superwrap 2 applied



Completed application

## Application Situation

No hot works were possible in the area due to the tank's location. A cold applied repair was required to repair this leak long term.

## Application Method

The area was prepared with an MBX Bristle Blaster to SSPC SP11. A cold plate bond was then applied using Belzona 1111. This plate was then encapsulated with Belzona Superwrap 2

## Belzona Facts

This repair was carried out in 1.5 days, allowing a fast return to service for the customer

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve