

BELZONA REBUILDS WEAR RING SEATS

ID: 906

Industry: *Power*
Application: *CEP-Centrifugal Pumps*
Substrate: *Cast Iron*
Products: *Belzona® 1311 (Ceramic R-Metal)*

Customer Location: *Power plant - Tulsa, Oklahoma, USA*
Application Date: *October 2007*

Problem

Severe erosion corrosion



Photograph Descriptions

* Pump to be rebuilt , * Surface being prepared , * Wear rings used as formers for Belzona® 1311 rebuild , * Scrapers used to complete application ,

Application Situation

Auxiliary pump casing

Application Method

Application carried out in accordance with Belzona System Leaflet CEP-2. Wear rings used as formers. After curing excess Belzona® 1311 removed with scrapers.

Belzona Facts

Belzona repair carried out quickly, postponed pump replacement, and improved pump efficiency.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve