

BELZONA RESTORES KITCHEN WASHROOM FLOOR

ID: 909

Industry: General Industry

Customer Location: Hospital - Albuquerque, New Mexico, USA

Application: FPA-Floor Problem Areas

Application Date: October 2007

Substrate: Terrazzo

Products: Belzona® 4111 (Magma Quartz
 Belzona® 5231 (SG Laminate)

Problem

The terrazzo floor had degraded from constant cleaning and contact with cleaning solutions.



Photograph Descriptions

* Close-up of original damaged floor , * Heavy damage in washdown room , * Finished floor where washing machine goes , * Finished floor from outside hallway ,

Application Situation

Hospital kitchen washroom floor

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Belzona® 5231 was applied and extra grit broadcast on top.

Belzona Facts

A competitive bid was placed for the removal of existing surface and new terrazzo floor applied. Belzona was faster, cleaner, and less expensive than the other process.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024