

BELZONA RESTORES KITCHEN WASHROOM FLOOR

ID: 909

Industry: *General Industry*

Customer Location: *Hospital - Albuquerque, New Mexico, USA*

Application: *FPA-Floor Problem Areas*

Application Date: *October 2007*

Substrate: *Terrazzo*

Products: *Belzona® 4111 (Magma Quartz
 Belzona® 5231 (SG Laminate)*

Problem

The terrazzo floor had degraded from constant cleaning and contact with cleaning solutions.



Photograph Descriptions

* Close-up of original damaged floor , * Heavy damage in washdown room , * Finished floor where washing machine goes , * Finished floor from outside hallway ,

Application Situation

Hospital kitchen washroom floor

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Belzona® 5231 was applied and extra grit broadcast on top.

Belzona Facts

A competitive bid was placed for the removal of existing surface and new terrazzo floor applied. Belzona was faster, cleaner, and less expensive than the other process.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve