

BELZONA PROTECTS CONTAINMENT AREA

ID: 914

Industry: Power
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete
Products: Belzona® 4111 (Magma Quartz)
Belzona® 4311 (Magma CR1)

Customer Location: Power Project - Bastrop, Texas, USA
Application Date: November 2007

Problem

The previous coating had failed causing significant damage to the underlying concrete.



Photograph Descriptions

* Containment area prior to being coated , * Area prepared and leveled with Belzona® 4111 , * First coat of Belzona® 4311 being applied , * Completed application ,

Application Situation

Containment area for water treatment chemicals.

Application Method

The application was carried out in accordance with Belzona System Leaflets TCC-9 & 15

Belzona Facts

Previous attempts to coat this area had failed due to the chemical concentration. Belzona was chosen for its high chemical resistance. The two color system was also seen as an advantage as it will show when the coating needs to be touched up.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve