

Belzona Repairs Conveyor Belt

ID: 9213


Industry: *Mining & Quarrying*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Botswana*
Application Date: *August 2015*

Substrate: *Rubber*
Products: *Belzona 2131 (D & A Fluid Elastomer), Belzona 2911 (Elastomer QD Conditioner), Belzona 9111 (Cleaner Degreaser)*

Problem

A 10 meter section of the top layer rubber on a belt wore out.



Condition of belt

After application

Application Situation

The client needed a fast solution to assist them until the next outage.

Application Method

After abrading the belt, it was cleaned and degreased with Belzona 9111. A thin layer of Belzona 2911 Conditioner was applied to the damaged section.

Once the conditioner was touch dry, Belzona 2131 was applied and allowed to fully cure.

Belzona Facts

Instead of shutting the entire section down to replace the belt, Belzona saved the client time and money.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve