

SANDSTONE MULLION REPAIRS WITH BELZONA

ID: 925

Industry: *Buildings & Structures*

Customer Location: *Private Householder, Scotland*

Application: *WPA-Wall Problem Areas*

Application Date: *July 2003*

Substrate: *Red Sandstone*

Products: ** Belzona® 4141 (Magma Build) ,*

Problem

The cracks were getting worse due to frost damage in the winter months and previous attempts at concrete repairs had failed at the bond lines.



Photograph Descriptions

- * The problem. Note the grooving of the sandstone. ,
- * Belzona® 4141 being applied as a skim coat. ,
- * Finished application. ,
- * Inspected December 2007. ,

Application Situation

Householder had a problem of cracks in the sandstone Mullions of his bay windows.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-4. The cracks were opened out and filled prior to the whole mullion being skimmed with Belzona® 4141 tinted to match the colour. The original grooving on the stone was replicated in the Belzona® 4141.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA®
Repair • Protect • Improve

Belzona Facts

If the Mullions had not been repaired then it would have resulted in them becoming unstable. Traditional repair Methods had failed and replacement units were unavailable.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Copyright © Belzona International Limited 2025