

# Food manufacturing facility has Belzona repair End Quote refrigerator floor

ID: 9270

Industry: Food & Drink

Customer Location: Oklahoma City, Oklahoma

Application: FPA-Floor Problem Areas

Application Date: February 2024

Substrate: Concrete

Products: Belzona 4154 (Bulkfill Resin), Belzona 5811 (Immersion Grade)

## Problem

The floor in this refrigerator has been sitting on sub zero temperatures for 25 years. Constant freezing and unfreezing has left the concrete floor in very bad condition. In some areas it had up to two inches of concrete loss.



Area prior to application

Commencement of application

Belzona 5811 applied to area

Application completed

## Application Situation

The only down time the customer had was over a long weekend. This floor was not suitable for food refrigeration and had to be taken care of as soon as possible. The preparation cleaning resurfacing and coating of this floor was done in three days. The customer is extremely happy with the outcome of the floor and has three more refrigeration units to be done shortly with Barzona repair system.

## Application Method

The Belzona products were applied by hand

## Belzona Facts

Belzona is the only coating supplier that is trusted by this food facility. Over the last few years multiple repairs has been done to this facility using only Belzona products.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

