

Cable Repair Conducted with Belzona 2221!

ID: 9287

Industry: Mining & Quarrying
Application: SHM-Solids Handling Machinery

Customer Location: India
Application Date: 2023

Substrate: Rubber
Products: Belzona 2211 (MP Hi-Build Elastomer), Belzona 2921 (Elastomer GP Conditioner)

Problem

The underground mines cable outer sheets had become damaged due to very rough mining surface and dusty conditions. These mines are situated 200 to 500 metres deep, and damage like this can cause serious issue for water ingress.



The damaged cable



After surface preparation and Belzona 2921 (Elastomer GP Conditioner) was applied



Finished application with Belzona 2211 (MP Hi-Build Elastomer) applied on the damaged areas.

Application Situation

The alternative solution is to cut the portion of the cable and re join them together using a cable kit; however, by doing this, it does not give proper shape to the cable and takes 24 hours for the repair to cure. The Belzona solution offered a faster and more durable repair. However, the key selling point for the client was that the repair maintained the shape of the existing cable. They also required a cold repair that could offer a long-term solution and be applied in situ. No competitor is able to offer all of these benefits, and, most importantly, the quick application turnaround. Belzona 2211 (MP Hi-Build Elastomer) along with Belzona 2921 (Elastomer GP Conditioner) was used for the application.

Application Method

First the loose rubber was removed, and the application area roughened before applying Belzona 2921 (Elastomer GP Conditioner). The conditioner required to become touch dry and then Belzona 2211 (MP Hi-Build Elastomer) could be applied to the damaged areas. One repair takes approximately 2-3 hours.

Belzona Facts

This client was satisfied with the application as keeping these cables in service is critical to the running of the mine. This solution was won through product demonstrations and face-to-face meetings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve