

# BELZONA REFURBISHES LABORATORY WORKTOPS

ID: 937

Industry: *Water / Wastewater*  
Application: *WPA-Wall Problem Areas*  
Substrate: *unknown*  
Products: *Belzona® 5811 (Immersion Grade)*

Customer Location: *State Health Dept.*  
Application Date: *March 2005*

## Problem

*Severely degraded counter tops needed to be resurfaced with a chemically resistant coating.*



## Photograph Descriptions

\* Sink in lab before work , \* Fume cupboard before work , \* Sink after coating , \* Counter top after coating ,

## Application Situation

State Health Dept was building new facility and needed to extend life of existing facility lab counter tops

## Application Method

Application carried out in accordance with modified Belzona System leaflet FPA-3. Special care was taken to clean sand the surfaces. Belzona® 5811 applied over-thickness with a trowel to create a self levelling coat.

## Belzona Facts

Saved tens of thousands of dollars on replacements. In December 2007 Facilities Manager reports all is well, no complaints from workers.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve