

# Belzona Super wrap on a concrete stand for a pipe at a power station

ID: 9377

Industry: Power  
Application: WPA-Wall Problem Areas  
Substrate: Concrete  
Products: Belzona 1982 (SuperWrap II), Belzona SuperWrap

Customer Location: Oklahoma City  
Application Date: March 2024

## Problem

The concrete pedestal holding up a pipe formed a crack over the years of exposure to the elements.



Power plant water cooling pipe pedestal and crack



Superwrap II starting being applied



Second wrap on pedestal



Final picture with consolidation tape

## Application Situation

Cracks were injected and pinned before a two wrap system was applied.

## Application Method

Done by hand .

## Belzona Facts

Belzona was the preferred way to repair this concrete pedestal

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve