

# Belzona coating a acid drain with 4311

ID: 9389

Industry: *Not Specified*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete*  
Products: *Belzona 4311 (Magma CR1)*

Customer Location: *Oklahoma*  
Application Date: *December 2023*

## Problem

*The customer was getting chemical attack on the concrete*




Small chemical drain being coated first coat with Belzona 4311



First coat of Belzona 4311



Second and final coat of Belzona 4311.



Second drain, application with Belzona 4311

## Application Situation

This job was done at a pharmaceutical company and being such the job had to be done on a weekend behind seals doors for the dust.

## Application Method

This entire job was done by hand tools.

## Belzona Facts

Belzona is widely used in this facility and they trust the chemical resistance from Belzona 4311

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025